



10th IWA-ASPIRE CONFERENCE
AND WATER NEW ZEALAND
CONFERENCE & EXPO
Christchurch Ōtautahi
29 September - 3 October 2025



EMBRACING VIGILANCE

Lutra.



Richard Slight, Dora Luo

*Lutra NZ richard.slight@lutra.com
**Hamilton City Council dora.luo@hcc.govt.nz



INTRODUCTION


Hamilton City Council (HCC) owns and operates the Waioira WTP, treating water from the Waikato River. Principle 1 of drinking water safety is that a high standard of care should be embraced. What happens when a treatment barrier, though still effective, is not performing correctly? This poster outlines responses following an adverse impact directly linked to one filter refurbishment and how HCC resolved these issues in a timely manner before the risk was realised and impacted capacity and supply issues.

Filter #1 is one of 10 rapid gravity filters using a dual media design of expanded pumice and fine sand. Filter #1 media and ceramic nozzles were replaced in October 2022. In January 2022, higher backwash pressure and shorter run times were observed and water production volumes reduced.

HIGHLIGHTS

- Filter #1 at Waioira WTP performed poorly after media and nozzle renewal.
- A working group was formed to assess the issues.
- Issues were identified and rectified and changes implemented to prevent the issues occurring in the future.

METHODS




- High Backwash Pressure
- Short Filter Run Time
- Low backwash flow
- High clean bed head loss
- Uneven flow distribution

- Valve Failure
- Plenum blockage
- Nozzles & Stems
- Air lock
- Finer media
- Laterals blockage

- Valve performance investigation
- CCTV Plenum
- Visual observations of media fluidisation
- Pilot filter comparisons
- Check nozzles / compare performance
- Breather/manometer pipe on plenum
- Measure head loss in situ from the base of the media
- In situ media grading comparisons
- Relocate media to performing filter and check change in head loss


DISCUSSION



The media This was the first filter with a complete media replacement to PCDM (0.3 - 0.6mm) sand and 0.6 - 1.2 mm silicon sponge (expanded pumice). It was discovered through media sampling and pilot filter runs that the smallest sand grains migrated to the top layer, filling voids and creating a fine top layer that restricted flow. Prior to this, filters had a larger sponge grade (no longer available) so void spaces were much larger and head losses therefore lower.

RESULTS



SYMPTOMS



FINDINGS

Construction Faults

- Laterals set at different heights in the filter floor
- Nozzle depth into pipe varies based on lateral height




Supplier Fault

- Installed ceramic nozzles were 7 mm thinner than previous

Silicon Sponge Particle Size Distribution	
Size (mm)	Percent Passing
2.360	100
1.180	88
0.600	37
0.425	29
0.300	16
0.150	1
0.075	0

Media Specification

- Fine sand (0.3 to 0.6 mm) from the lower media layer migrated into the top layer.




REMEDIAL ACTIONS

- The existing nozzles were cleaned and reinstated
- Nozzles stems were each checked and trimmed to ensure clearance to the invert of the lateral
- Filter media was replaced with new dual combination to prevent sand migration
- Methodologies established for future works based on the lessons learnt
- QA process established for individual work packages

OUTCOMES

- Immediate improvement to backwash and filter performance.
 - Backwash pressure reduction from > 75 kPa to 50 kPa
 - Backwash flow from 32.5 m³/min to 36 m³/min
 - Filter run times from 48 hours to 96 hours
 - Reduced filter head losses from > 2m to < 1.5m
- Following 2 filters refurbishment to date have no issues. "best one ever" – Operations Manager

CONCLUSIONS



- This case highlights the importance of **Principle 1 of safeguarding drinking water** - taking a high level of care.
- The formation of a working group not only restored the Sand Filter 1's performance but also created a framework for better planning of future refurbishment.